

# Post-Tensioning Inspection and Rehabilitation of the I-526 Wando River Bridge

Nick Amico, PE

Senior Bridge Engineer



“The Post-Tensioning Institute has met the standards and requirements of the Registered Continuing Education Program. Credit earned on completion of this program will be reported to RCEP at RCEP.net. A certificate of completion will be issued to each participant. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the RCEP.”



# Copyright materials

This educational activity is protected by U.S. and International copyright laws. Reproduction, distribution, display and use of the educational activity without written permission of the presenter is prohibited.

© Post-Tensioning Institute 2021

# Learning Objectives

At the end of this presentation, you will be able to...

- Describe some NDE methods available for evaluating the condition of external tendons
- Describe the characteristics necessary to determine quality of tendon grout
- Describe a technique for supplementing external draped tendons
- Explain the importance of incorporating replaceable tendon details

# Topics

- Structure Overview
- Assessment Phase
- Remediation and Repairs
- Summary



Structure  
Overview


2021 **pti** VIRTUAL CONVENTION

April 19-23 | Online

# Structure Overview



# Structure Overview



# Structure Overview

ADT: 35,850 (Each Structure)

ADTT: 8,960 (Each Structure)

Of the three crossings,  
Wando carries:

- 39% of the total traffic
- 87% of the truck traffic



# Structure Overview

Erected: 1989

Opened: 1991

Construction cost: \$32M

Total Length: 7,900ft (Each)

Max Span Lengths: 400ft



Approach Span Lengths: 150ft

Total Number of Spans: 49 (Each)





# Structure Overview

- Precast, Post-Tensioned Segmental Construction
- Approach Spans erected with the Span-by-Span Method
- Main Spans erected with the Balanced Cantilever Method utilizing a temporary piers
- Combination of Internal and External Tendons
  - 600 External Draped Longitudinal Tendons
  - 792 Internal Longitudinal Tendons



# Structure Overview

- Approach Span Erection







# Structure Overview

- Approach Span Erection




# Structure Overview

- Approach Span Erection



# Structure Overview

- Approach Span Erection



# Structure Overview


- Approach Span Erection



- All original anchors except one per web are uninspectable and unreplaceable.
- The tendon with the accessible anchor deviates into the top slab for multiple segments, including over the pier segment, preventing its replacement.
- No accommodation for future tendons

# Structure Overview

- Main Span Unit Erection






# Structure Overview



# Structure Overview

- M1 Tendon Failure
  - 19 Strand Tendon
  - 1,010 ft long
  - External Tendon
  - Continuous between Piers 24-29
  - Passing 8 Diaphragms



# Structure Overview

- Response:
  - No other distress evident
  - Installed crack monitors at key locations
  - Closed one traffic lane to reduce load and provide a work zone on the deck
  - Modeled and analyzed main span unit
  - Installed one supplemental tendon
  - Detensioned and replaced M1 tendon





Assessment  
Phase

# Assessment Phase

## Limited Inspection, Testing, and Analysis Program


- Determine if grout deficiencies were present
- Determine the extent and significance of these deficiencies
- Identify sources and extent of corrosion in the external tendons
- Propose courses of remedial action



# Assessment Phase

## Tendon Protection

- Levels of tendon protection:
  - Structure
  - Duct
  - Grout
- Physical barrier to water and oxygen
- High pH grout forms a protective oxide film on the strand



# Assessment Phase

## Deficiencies to look for

- Physical deficiencies
  - Cracks, spalls, voids
  - Segmented, unsealed ducts
  - Cracked or punctured ducts
  - Unprotected grout ports
- Physical grout deficiencies
  - Soft grout
  - Segregated grout
  - Voids and poor grout cover
  - Microcracking
- Chemical deficiencies
  - Carbonation
  - High chloride content
  - High sulfate content



# Assessment Phase

Program included:

- M1 Tendon Investigation
- Visual tendon and structure inspections
  - Borescope inspections of anchors and high points
- Magnetic flux testing
- Capacitive probe inspection
- Grout testing
- FE Modeling / Load Rating



# Assessment Phase



## M1 Investigation



# Assessment Phase

## M1 Investigation

- Tendon and Grout condition observations



# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential (ASTM C876)
  - Indicated no active corrosion for all tendon samples




# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential
- Corrosion rate
  - Linear polarization resistance test
  - Results were very low  
0.04 mpy - 0.24 mpy

$$I_{corr} = \frac{\beta_a \cdot \beta_c}{2.3 \cdot R_p \cdot (\beta_a + \beta_c)}$$

$$CR = \frac{I_{corr} \cdot k \cdot EW}{d \cdot A}$$



# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential
- Corrosion rate
- Grout tests
  - Grout alkalinity (pH)
  - Chloride content (AASHTO T-260)
  - Sulfate content (ASTM C114)
  - Moisture content (ASTM C566)
  - Petrographic analysis



# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential
- Corrosion rate
- Grout tests
- Tensile strength testing (ASTM A1061)
- Duct material tests (ASTM D3350, PTI/ASBI M50.3)

# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential
- Corrosion rate
- Grout tests
- Tensile strength testing (ASTM A1061)
- Duct material tests
- Summary

## Away from rupture location

- Strand was in good condition with very little corrosion since construction
- Corrosion potential showed low probability of active corrosion
- Measured corrosion rates were low
- Grout: high pH, low chlorides, normal sulfates, normal moisture content, but with high entrapped air voids and grout fracture
- In short: no significant corrosion would be expected if encased in grout

# Assessment Phase

## M1 Investigation

- Grout condition observations
- Corrosion potential
- Corrosion rate
- Grout tests
- Tensile strength testing (ASTM A1061)
- Duct material tests
- Summary





## At the rupture location

- Severe corrosion of the strand
- Duct was approximately 80% empty
- pH was very low
- Water infiltration
- In short: large void at the high point of the tendon left the strand unprotected

# Assessment Phase

## Visual Tendon and Structure Inspections


- Walk-through inspection of both structures
- Borescope inspections of anchors and high points



# Assessment Phase

## Visual Tendon and Structure Inspections

- Total of 300 borescope inspections performed
  - 270 Accessible external tendon anchors investigated
  - 30 External tendon high points investigated
- Various deficiencies included
  - Grout voids
  - Exposed strand
  - Corrosion
  - Soft grout
  - Water leaking



# Assessment Phase

## Visual Tendon and Structure Inspections

- Leaking segment joints
- Slack tendon (Span 16)
  - No evidence of water infiltration, corrosion, or poor grout
- Slack strands
  - Fully grouted in place, indicating occurrence during construction



# Assessment Phase

## Magnetic Flux Testing



- Locates areas of steel section loss due to corrosion, wire pitting, or breakage
- Applies a magnetic field to induce flux paths between the poles
- Magnetic field “leaks” at points of section loss and the change is detected by sensors
- Changes are correlated to section loss based on previous calibrations
- Magnet and sensors on a wheeled frame that is moved along the tendon free-length
- Data is reported in real time to the operator



# Assessment Phase

## Magnetic Flux Testing

- Total of 24,525 lf of external tendons were investigated
- Locations of indicated section loss were flagged for monitoring or opening for investigation
- Openings at the five tendons in the highest category revealed minor corrosion that did not warrant further testing or replacement



# Assessment Phase

## Capacitive Probe Inspection

- Locates defects including presence of voids, water, white paste, and soft grout
- Monitors the capacitance between two electrodes
- Contrast in permittivity between different materials and moisture content allows measurement of capacitance variation.
- Inspection depth of 30mm
- Moved along duct until a defect is located and rotated around duct to check full section at the point of interest
- Limitations:
  - Requires HDPE ducts with cementitious grout
  - Metallic surfaces within 30cm can interfere and alter the measured frequencies
  - Space required for rotations is 30cm; cannot inspect tendons close to the webs

USA2217 - Wando Capacitive Probe Inspection




Analysis Report sheet

EB SP13 SD M3

PART 1


Rotation analysis



# Assessment Phase

## Capacitive Probe Inspection

- Performed 44,445 LF of tendon scanning between both structures



- Located voids of various size and severity
  - Some larger voids, similar to image
  - Some areas of heavily air-entrained grout
  - Small separations between the grout and to of duct
- No evidence of significant distress identified

# Assessment Phase

## Grout Testing


- In-situ testing
  - Corrosion potential
  - Corrosion rate
  - Grout alkalinity (pH)
- Laboratory testing
  - Chloride content
  - Sulfate content
  - Moisture content
  - Petrographic analysis
- Findings
  - Grout was predominantly good quality with a high pH
  - Moisture content was typically normal
    - a few locations were elevated, which could signify water infiltration
  - Chloride content was typically low
  - Sulfate content was low
  - No corrosion potentials indicated high probability for active corrosion
  - All corrosion rates measured low (<0.3 mpy)

*No significant tendon corrosion is expected for tendons that are encased in grout*

# Assessment Phase

## Modeling and Limited Load Rating


- Developed 3D Time-Dependent Staged Construction Models with LARSA 4D
  - Main Span Unit
  - Typical Approach Span Unit
  - Transverse Analysis Models
- Construction sequences based on contract plans, anchor configuration, and photos
- Developed calculations for service stresses, ultimate moment, and shear & torsion



# Assessment Phase

## Modeling and Limited Load Rating

- Evaluated the structures for
  - Original Design Code: AASHTO Standard Specifications, 1977
  - Current Design Code: AASHTO LRFD, 8<sup>th</sup> Edition
- All subsequent design and final load rating was performed with LRFD and LRFR
- Determined safety for continued service with various tendon loss “what-if” scenarios



# Assessment Phase

## Condition Summary

- M1 tendon failed due to the existence of a large grout void and water infiltration
- Grout throughout the structure was of reasonably good quality and would protect tendons as intended if fully encased
- Water infiltration was observed in several locations
- Several leaking segment joints
- One detensioned external tendon
- Use of couplers and embedding of anchors precludes direct replacement of most tendons




Remediation  
and Repairs

# Remediation and Repairs

## Main Span Supplemental Tendons

- Second WB tendon rupture, May 2018
- Rupture at same location as M1 tendon
- Closed WB structure; crossovers used to shift WB lanes to EB structure



# Remediation and Repairs

## Main Span Supplemental Tendons


- Two supplemental tendons permanently installed in both structures
- Deck repairs performed
- Metallurgical testing
- Bridge reopened after 19 days



# Remediation and Repairs

## Stop the Water


- Phase 1:
  - Locate and seal all exposed grout ports on the deck
    - Locations cored, sides roughened, cleaned, and filled with epoxy grout
  - Repaired deck spalls and delaminations
  - Sealed deck repairs, cracks, leaking segment joints and all closure pours with high molecular weight methacrylate (HMWM)
    - Extended limits of HMWM at select locations
- Phase 2:
  - Polyester polymer concrete (PPC) overlay
  - Scheduled Spring 2021



# Remediation and Repairs

## Replace M2 Tendons

- Advanced corrosion was identified on two additional tendons in the WB structure
- Detensioning required prior to replacement
  - Method used for M2s differed from previous rupture replacements
  - M2s were completely intact, but had partially corroded




*Detensioning Plan for Ruptured Tendons M1 and M4*

# Remediation and Repairs

## Replace M2 Tendons

- Detensioning of ruptured M1 and M4 tendons
  - Install heavy duty clamps every 4ft along the full length of the tendon
  - Grout removed at specific locations on either side of diaphragms
  - Strands cut with powered cutoff saw alternately on either side of P25 to match broken strands at P27 and balance the tendon force.
  - Cut strands at P28 to match P27
  - Cut one strand at each point sequentially until all strands are cut
  - Remove the tendons from the diaphragms by pulling the tails




Detensioning Plan for Ruptured Tendons M1 and M4

# Remediation and Repairs

## Replace M2 Tendons

- Detensioning of intact M2 tendons
  - Given the condition of the tendon, plan was developed to minimize risk and have no one in the main span unit at the time of detensioning
  - Based on previous ruptures, tendons would slip in the transition diaphragms, reducing the unbalanced tension on the diaphragms as well as the tension in the adjacent spans
  - Tendons were secured along the length of the tension to prevent whiplash
  - Detension sequence A-B-C-D-E




*Detensioning Plan for Intact Tendons M2-L and M2-R*

# Remediation and Repairs

## Replace M2 Tendons

- Detensioning of intact M2 tendons
  - Four remote controlled power saws were used with a control unit on the deck
  - Cameras were installed with each saw and in each span
  - Personnel were cleared from the inside the unit and not permitted to reenter until the condition was confirmed through the cameras
  - Short term traffic closure during cutting until cleared by SCDOT




*Detensioning Plan for Intact Tendons M2-L and M2-R*

# Remediation and Repairs

## Replace M2 Tendons


- M2-L and M2-R tendons were replaced one at a time
- Inspection of the tendons revealed corrosion, but was not as extensive as anticipated



# Remediation and Repairs

## P24 Segment Joint Repair


- Leaking and damaged joint at P24 diaphragm, both structures
- Joint further damaged in prior efforts to seal it
- Visible differential displacement under truck loads



# Remediation and Repairs

## P24 Segment Joint Repair

- Joint is between a pier segment and a typical segment
- Differential deck displacement at joint causing additional spalling and deterioration
- Needed to control the differential displacements, repair the deck, and seal the joint
- Deck is 8" thick (before milling) and very lightly reinforced, so limited shear capacity if a frame was added



# Remediation and Repairs

## P24 Segment Joint Repair



- Two-part solution:
  - Steel frame to limit the displacement of the deck
  - Precast drop slab to additional shear capacity to the deck
- Steel frame designed to be removeable to provide anchor access
- Drop slab is connected to the top slab with epoxy and a grid of post-tensioned rods for composite action



# Remediation and Repairs

## P24 Segment Joint Repair


- Finite element models (LUSAS and LARSA 4D) were used to determine:
  - Distribution of live loads into the steel frame
  - Permanent contact compression stress required to ensure composite behavior
  - Loadings imparted on the lightly reinforced bottom slab under the frame
  - Length of slab necessary to distribute shear stress
  - Final differential displacements



# Remediation and Repairs

## P24 Segment Joint Repair

- Drop slabs were precast inside the bridge
- Prefabricated Double-Corrosion Protection (DCP) Rods used to join slab and deck



# Remediation and Repairs


## P24 Segment Joint Repair

- DCP rods installed through core holes in top slab



# Remediation and Repairs


## P24 Segment Joint Repair



# Remediation and Repairs

## WB Span 16 Supplemental Tendons


- Draped portion of Tendon 4S found to be during assessment phase
- Several bulges in the HDPE duct
- Opened in two locations to reveal fractured grout
- Downstation end of tendon still had tension
- No evidence of corrosion or water infiltration of the tendon or at the diaphragm



# Remediation and Repairs

## WB Span 16 Supplemental Tendons

- Replacement challenges
  - Tendon is coupled to a tendon in the adjacent span
  - Tendon profile becomes internal to the bottom slab



# Remediation and Repairs


## WB Span 16 Supplemental Tendons

- Supplemental design requirements
  - Replace both shear and moment capacity
  - Must not prevent remediation for other tendons
- Supplemental design challenges
  - Diaphragms are small and congested with reinforcing and transverse PT
  - Top slab and interior haunches are relatively thin



# Remediation and Repairs


## WB Span 16 Supplemental Tendons



- Two new tendons, crossing at the midspan of Span 16
- Places all anchor blocks on the bottom slab → no impact to traffic
- Matches the  $V_p$  provided by the original tendon
- Doubles the number of strands crossing the midspan
- Provides redundancy for existing coupled tendon in adjacent span

# Remediation and Repairs

## WB Span 16 Supplemental Tendons




- Expandable to permit future supplemental tendons if necessary
- Deviators can accommodate replacement of all tendons in the span

# Remediation and Repairs

## WB Span 16 Supplemental Tendons


- Longitudinal and Transverse models developed in LARSA 4D
- Longitudinal design considered the controlling of:
  - Complete loss of existing tendon
  - Partial loss of existing tendon
- AASHTO LRFD



# Remediation and Repairs

## WB Span 16 Supplemental Tendons



- Local effects on existing structure evaluate with Solid Finite Element Modeling performed in LUSAS
  - Half span model take advantage of symmetry
  - Staged construction
  - Initial stress state loading to match full structure analysis



# Remediation and Repairs

## WB Span 16 Supplemental Tendons


- Anchor/Deviator
  - Anchors two 12-strand tendons
  - Deviates two 12-strand tendons
  - Tension slab distributes local tension behind anchors



# Remediation and Repairs

## WB Span 16 Supplemental Tendons



- Anchor/Deviator



# Remediation and Repairs

## WB Span 16 Supplemental Tendons

- Pier Segment Deviators
  - Designed to accommodate six tendons
  - Utilizes diabolos with preloaded HDPE
  - High point grout vents cast with deviator and accessible on deviator face



# Remediation and Repairs

## WB Span 16 Supplemental Tendons

- Pier Segment Deviators



# Remediation and Repairs

## WB Span 16 Supplemental Tendons

- Other Details



*PT bar anchors on exterior face of web*

*Span 16 Stressing*



*CFRP reinforcing at new access opening*






*Tendon impregnation*

# Remediation and Repairs

## WB Span 16 Supplemental Tendons

- 3D Drawings



# Remediation and Repairs

WB Span 16 Supplemental Tendons




An aerial photograph of a long, multi-lane bridge spanning a wide body of water. The bridge is supported by numerous tall, white, rectangular piers. The water is a deep blue, and the surrounding land is green with trees and some buildings. A circular graphic with a white background and a blue border is overlaid on the left side of the image, containing the word "Summary".

# Summary

# Summary

- Structure Overview
  - Regional importance of the structure
  - Original construction methods
- Assessment Phase
  - Investigation into the cause of the tendon rupture
  - Methods used to evaluate the condition of the PT system
- Remediation and Repairs
  - Tendon replacements
  - Creative applications of post-tensioning in repairing a segment joint
  - Concept for installing draped supplemental post-tensioning



This concludes the Educational Content of this activity



**FREYSSINET**

**Questions?**



**sixsense**

Nick Amico, PE  
nick.amico@hdrinc.com  
(704) 338-6708



**SIVA CORROSION SERVICES, INC.**  
Materials, Corrosion, and NDT Specialists

