38800 Country Club Drive, Farmington Hills, MI 48331

Telephone: (248) 848-3180

Fax: (248) 848-3181

www.post-tensioning.org

## **ERRATA**

## PTI DC45.1-12 Recommendations for Stay Cable Design, Testing, and Installation

## Sixth Edition, First Printing 2012 DC-45 Stay Cable Bridge Committee

The following errata item was added on January 8, 2014:

## Page 12, Fig. C3.1:




Fig. C3.1 – Fatigue safety philosophy. (Note:  $\Delta_1$  is quality assurance [17 MPa coupled bar, 69 MPa strand and uncoupled bar, 103 MPa wire] and  $\Delta_2$  is length effect, anchorage riser, safety [35 MPa].)